

General Environmental Incident Summary

Incident: 3831 **Date/Time Notice:** 7/23/2015 **DEM Incident No:**
Responsible Party: badlands hydrovac services llc
Date Incident: 7/20/2015 **Time Incident:** 1600 **Duration:**
County: Williams **Twp:** 154 **Rng:** 96 **Sec:** 1 **Qtr:**
Lat: 48.19342 **Long:** -102.97070 **Method:** Interpolation from map
Location Description: from Williston take 1804 east until approx. 1 mile before 105th ave nw scoria road towards south

Submitted By: Jason Brew **Affiliation:**
Address: po box 1639
City: watford city **State:** ND **Zip:**

Received By:

Contact Person: Jason Brew
po box 1639
watford city, ND

Distance Nearest Occupied Building: 0.75 Miles **Release Contained:** Yes

Type of Incident: fuel tank leak

Description of Released Contaminant: diesel fuel

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

drove of mate broke plug off of underneath tank

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

spill kit, then soil excavated and taken to trevita

Wastes Disposal Location: trevita

Agencies Involved:

Updates

Date: 7/23/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with responsible party via phone at 13:30. Discussions of the release indicated that the spill had been contained/removed and hauled to Tervita for disposal. Asked the responsible party to provide confirmation samples to verify cleanup. The responsible party indicated that they would obtain a third party consultant to document the cleanup and forward the results to the Department. More follow-up needed.

Date: 7/23/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release from fuel tank leak onto roadway. Follow-up is required.

Date: 9/15/2015 **Status:** Correspondence

Author: Stockdill, Scott

Updated Volume:

Notes:

Sample data submitted to the NDDoH. Sample results came back indicating the site has been properly cleaned up. A closure letter has been emailed to the responsible party.